

ASQ CQI

ASQ Certified Quality Inspector

For More Information – Visit link below:

<https://www.examsempire.com/>

Product Version

- 1. Up to Date products, reliable and verified.**
- 2. Questions and Answers in PDF Format.**



<https://examsempire.com/>

Visit us at: <https://www.examsempire.com/cqi>

Latest Version: 13.0

Question: 1

Which of the following statements best applies to the coordinate measuring machine?

Response:

- A. All of the above
- B. The Y axis is horizontal from front to back
- C. It can be used to measure roundness and radi
- D. The Z axis is vertical

Answer: A

Question: 2

Evidence of which of the following is normally required and can be as simple as retention of certificates and reports of calibration, or as complex as reproduction of the analyses demonstrating the uncertainties claimed for the measurements?

Response:

- A. Reproducibility
- B. Traceability
- C. Linearity
- D. Inspection

Answer: B

Question: 3

The area of a rectangle is 62.92 cm². If two of its sides measure 5.2 cm, what is the length of the other two sides?

Response:

- A. 26.3 cm
- B. 2.3 cm
- C. 12.1 cm
- D. 52.52 cm

Answer: C

Question: 4

A rectangle has dimensions $3 \frac{5}{8}$ inches and $6 \frac{3}{4}$ inches. Find the area of the rectangle to the nearest 0.1 in ².

Response:

- A. 24.5 in ²
- B. 25.7 in ²
- C. 25.2 in ²
- D. 22.8 in ²

Answer: A

Question: 5

Solve for x. $(8 - x) / 3 = 21$

Response:

- A. -55
- B. 55
- C. -71
- D. 71

Answer: A

Question: 6

Which of the following is a component of an attribute (data) sampling plan?

Response:

- A. Unit is inspected by its proximity to specifications
- B. Items are classified as Percent Defective
- C. Inspection method is more sophisticated
- D. Smaller sample size can be utilized

Answer: B

Question: 7

You are taking an inventory of dial indicators in an inspection shop and notice one that has a yellow face. What does this tell you?

Response:

- A. The indicator has a revolution counter
- B. It is a balanced indicator
- C. It has a resolution of .0001" or greater
- D. The readings will be in the metric system

Answer: D

Question: 8

Seriousness classifications for quality characteristics and defects are derived from

Response:

- A. specifications and failure evidence
- B. maintenance and machine downtime
- C. inspection error
- D. equipment and processes

Answer: A

Question: 9

A rectangle has dimensions $35\frac{3}{8}$ inches and $63\frac{1}{4}$ inches. Find the perimeter of the rectangle.

Response:

- A. $28\frac{3}{8}$
- B. $21\frac{7}{8}$
- C. $20\frac{3}{4}$
- D. $99\frac{1}{4}$

Answer: C

Question: 10

The sum of $45.29 + 8.4$ has how many significant digits?

Response:

- A. 2
- B. 3

- C. 4
- D. 1

Answer: B

Question: 11

Often inspection stations do not require full time presence. A usual practice is to collect such stations into a _____ so designed that it will occupy the full time of one person.

Response:

- A. Spot check
- B. 100% inspection
- C. Round robin
- D. Patrol beat

Answer: D

Question: 12

Which of the following is NOT necessary for team effectiveness?

Response:

- A. The team is accountable for specific measurable outcomes.
- B. Company management directly participates as a team member.
- C. A process exists for establishing goals and objectives.
- D. The team's purpose is clearly understood and supported by all members.

Answer: B

Question: 13

When surface plate is used with a v-block, dimensional measurements should be:

Response:

- A. Both Based on whether the plates are made with cast iron or granite plates and Taken from the v-block up
- B. Based on whether the plates are made with cast iron or granite plates
- C. Taken from the plate up
- D. Taken from the v-block up

Answer: C

Question: 14

The two mandatory criteria for software quality are:
Response:

- A. Reliability and Stability
- B. Reliability and Modifiability
- C. Stability and Compliance
- D. Compliance and Modifiability

Answer: D

Question: 15

On a control chart, what pattern occurs when there are eight points in a row falling on both sides of the central line and none of the points fall within the -1σ and the $+1\sigma$ limits?
Response:

- A. A trend
- B. Out of control point
- C. Run
- D. Mixture

Answer: D

Question: 16

Team progression begins with which stage when members cautiously explore boundaries of acceptable group behavior?
Response:

- A. Norming
- B. Storming
- C. Forming
- D. Performing

Answer: C

Question: 17

In which of the following is the presence of interference bands between the flat and the surface being tested, an indication that the surface is not parallel with the surface of the flat?

Response:

- A. Oscilloscope
- B. Optical flats
- C. Vernier height gage
- D. Gage block

Answer: B

Question: 18

Which of the following measures the preciseness of observations taken under the same conditions, which is achieved by computing the variance of such observations?

Response:

- A. Reproducibility
- B. Linearity
- C. Repeatability
- D. Stability

Answer: C

Question: 19

What is the primary purpose of audit working papers?

Response:

- A. Evidence of internal controls
- B. Subsequent audits of the same area
- C. Supporting document for audit report
- D. Audit personnel evaluation

Answer: C

Question: 20

The different measures for dispersion include which of the following?
Response:

- A. Mode, Range, Variance, Standard deviation.
- B. Range, Standard deviation and mode
- C. Range, Variance, Standard deviation.
- D. Variance, Standard deviation and mode.

Answer: C

Thank You for Trying Our Product

Special 16 USD Discount Coupon: NSZUBG3X

Email: support@examsempire.com

**Check our Customer Testimonials and ratings
available on every product page.**

Visit our website.

<https://examsempire.com/>